Church security guidance

The protection of stained glass windows



All external windows containing stained, painted or engraved glass, should be externally protected by stainless steel grilles or polycarbonate sheeting which entirely covers the window.

In the case of polycarbonate sheeting, care should be taken to allow for ventilation.

Installation

The installation of such protection is a specialised matter and should only be entrusted to a glazier or builder well experienced in installing such protection and in working on church buildings.

Important notes

Permission may be required from the RCB for the protection of windows and they should therefore be consulted at an early stage and prior to any work being carried out.

It is the responsibility of the party implementing the above specification to ensure that the implementation does not contravene any statutory or Local Authority requirements, eg under the Safety, Health & Welfare at Work Act.



Photographs

It is important to take photographs of all stained glass windows. Although a general shot of a window is helpful, these often do not provide sufficient detail for a stained glass restorer. More detailed photographs are needed. Heads, hands, draperies, landscapes and wildlife elements are the most difficult to replicate. Consider the lighting; ensure that you photograph west windows in the morning and east windows in the afternoon.

Need to contact us?

For further advice Ecclesiastical customers can call our Risk Management Team on **01 619 0300** (Monday to Friday 9am - 5pm, excluding bank holidays)

This guidance is provided for information purposes and is general and educational in nature and does not constitute legal advice. You are free to choose whether or not to use it and it should not be considered a substitute for seeking professional help in specific circumstances. Accordingly, Ecclesiastical Insurance Office plc and its subsidiaries shall not be liable for any losses, damages, charges or expenses, whether direct, indirect, or consequential and howsoever arising, that you suffer or incur as a result of or in connection with your use or reliance on the information provided in this guidance except for those which cannot be excluded by law. Where this guidance contains links to other sites and resources provided by third parties, these links are provided for your information only. Ecclesiastical is not responsible for the contents of those sites or resources. You acknowledge that over time the information provided in this guidance may become out of date and may not constitute best market practice.



Ecclesiastical Insurance Office plc is regulated by the Central Bank of Ireland.

Ecclesiastical Insurance Office plc Reg. No. 24869. Registered in England at Benefact House, 2000 Pioneer Avenue, Gloucester Business Park, Brockworth, Gloucester, GL3 4AW, United Kingdom. Registered Branch in Dublin, Ireland. Reg No. 902180. 2nd Floor, Block F2, EastPoint, Dublin 3. Authorised by the Prudential Regulation Authority and regulated by the Financial Conduct Authority and the Prudential Regulation Authority in the United Kingdom (Firm Reference Number 113848).